# CPE2026-001 – Vulnerabilities Mitigation/Remediation for Small Office Multifunction Printers and Laser Printers – 15 January 2026 (Updated: 20 February 2026)

## Affected Products/Models

* Added on 13 February 2026
** Added on 20 February 2026

| Products | Affected Firmware Version | Fix Firmware Version | CVE-2025-14231 | CVE-2025-14232 | CVE-2025-14233 | CVE-2025-14234 | CVE-2025-14235 | CVE-2025-14236 | CVE-2025-14237 |
|---|---|---|---|---|---|---|---|---|---|
| imageFORCE 1440* | Main Controller v02.02 and earlier | Main Controller v03.01and higher | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ |
| imageFORCE 1440F* | Main Controller v02.02 and earlier | Main Controller v03.01and higher | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ |
| imageFORCE 1440P* | Main Controller v02.02 and earlier | Main Controller v03.01and higher | ✓ | ✓ | ✓ | ✓ | ✓ | | ✓ |
| imageFORCE 1440Pr* | Main Controller v02.02 and earlier | Main Controller v03.01and higher | ✓ | ✓ | ✓ | ✓ | ✓ | | ✓ |
| imageFORCE C1333* | Main Controller v02.01 and earlier | Main Controller v02.02and higher | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ |
| imageFORCE C1333F* | Main Controller v02.01 and earlier | Main Controller v02.02and higher | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ |
| imageFORCE C1333P* | Main Controller v02.01 and earlier | Main Controller v02.02and higher | ✓ | ✓ | ✓ | ✓ | ✓ | | ✓ |

| Products | Affected Firmware Version | Fix Firmware Version | CVE-2025-14231 | CVE-2025-14232 | CVE-2025-14233 | CVE-2025-14234 | CVE-2025-14235 | CVE-2025-14236 | CVE-2025-14237 |
|---|---|---|---|---|---|---|---|---|---|
| imageRUNNER 1643i II | Main Controller v06.02 and earlier | Main Controller v07.01 and higher | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ |
| imageRUNNER 1643iF II | Main Controller v06.02 and earlier | Main Controller v07.01 and higher | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ |
| i-SENSYS LBP233dw | Main Controller v06.02 and earlier | Main Controller v07.01 and higher | ✓ | ✓ | ✓ | ✓ | ✓ | | ✓ |
| i-SENSYS LBP236dw | Main Controller v06.02 and earlier | Main Controller v07.01 and higher | ✓ | ✓ | ✓ | ✓ | ✓ | | ✓ |
| i-SENSYS LBP243dw II* | Main Controller v02.02 and earlier | Main Controller v03.01and higher | ✓ | ✓ | ✓ | ✓ | ✓ | | ✓ |
| i-SENSYS LBP243dw** | Main Controller v07.01 and earlier | Main Controller v07.02and higher | ✓ | ✓ | ✓ | ✓ | ✓ | | ✓ |
| i-SENSYS LBP246dw II* | Main Controller v02.02 and earlier | Main Controller v03.01and higher | ✓ | ✓ | ✓ | ✓ | ✓ | | ✓ |
| i-SENSYS LBP246dw** | Main Controller v07.01 and earlier | Main Controller v07.02and higher | ✓ | ✓ | ✓ | ✓ | ✓ | | ✓ |
| i-SENSYS LBP631Cw | Main Controller v06.02 and earlier | Main Controller v07.01 and higher | ✓ | ✓ | ✓ | ✓ | ✓ | | ✓ |
| i-SENSYS LBP633Cdw | Main Controller v06.02 and earlier | Main Controller v07.01 and higher | ✓ | ✓ | ✓ | ✓ | ✓ | | ✓ |

| Products | Affected Firmware Version | Fix Firmware Version | CVE-2025-14231 | CVE-2025-14232 | CVE-2025-14233 | CVE-2025-14234 | CVE-2025-14235 | CVE-2025-14236 | CVE-2025-14237 |
|---|---|---|---|---|---|---|---|---|---|
| i-SENSYS LBP646Cdw* | Main Controller v02.01 and earlier | Main Controller v02.02and higher | ✓ | ✓ | ✓ | ✓ | ✓ | | ✓ |
| i-SENSYS LBP647Cdw* | Main Controller v02.01 and earlier | Main Controller v02.02and higher | ✓ | ✓ | ✓ | ✓ | ✓ | | ✓ |
| i-SENSYS LBP673Cdw II* | Main Controller v02.01 and earlier | Main Controller v02.02and higher | ✓ | ✓ | ✓ | ✓ | ✓ | | ✓ |
| i-SENSYS LBP673Cdw** | Main Controller v07.04 and earlier | Main Controller v08.01and higher | ✓ | ✓ | ✓ | ✓ | ✓ | | ✓ |
| i-SENSYS MF453dw | Main Controller v06.02 and earlier | Main Controller v07.01 and higher | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ |
| i-SENSYS MF455dw | Main Controller v06.02 and earlier | Main Controller v07.01 and higher | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ |
| i-SENSYS MF461dw II* | Main Controller v02.02 and earlier | Main Controller v03.01and higher | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ |
| i-SENSYS MF461dw** | Main Controller v07.01 and earlier | Main Controller v07.02and higher | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ |
| i-SENSYS MF463dw II* | Main Controller v02.02 and earlier | Main Controller v03.01and higher | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ |
| i-SENSYS MF463dw** | Main Controller v07.01 and earlier | Main Controller v07.02and higher | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ |

| Products | Affected Firmware Version | Fix Firmware Version | CVE-2025-14231 | CVE-2025-14232 | CVE-2025-14233 | CVE-2025-14234 | CVE-2025-14235 | CVE-2025-14236 | CVE-2025-14237 |
|---|---|---|---|---|---|---|---|---|---|
| i-SENSYS MF465dw II* | Main Controller v02.02 and earlier | Main Controller v03.01and higher | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ |
| i-SENSYS MF465dw** | Main Controller v07.01 and earlier | Main Controller v07.02and higher | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ |
| i-SENSYS MF552dw | Main Controller v06.02 and earlier | Main Controller v07.01 and higher | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ |
| i-SENSYS MF553dw | Main Controller v06.02 and earlier | Main Controller v07.01 and higher | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ |
| i-SENSYS MF651Cw | Main Controller v06.02 and earlier | Main Controller v07.01 and higher | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ |
| i-SENSYS MF655Cdw | Main Controller v06.02 and earlier | Main Controller v07.01 and higher | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ |
| i-SENSYS MF657Cdw | Main Controller v06.02 and earlier | Main Controller v07.01 and higher | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ |
| i-SENSYS MF664Cdw* | Main Controller v02.01 and earlier | Main Controller v02.02and higher | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ |
| i-SENSYS MF667Cdw* | Main Controller v02.01 and earlier | Main Controller v02.02and higher | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ |
| i-SENSYS MF752Cdw II* | Main Controller v02.01 and earlier | Main Controller v02.02and higher | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ |

| Products | Affected Firmware Version | Fix Firmware Version | CVE-2025-14231 | CVE-2025-14232 | CVE-2025-14233 | CVE-2025-14234 | CVE-2025-14235 | CVE-2025-14236 | CVE-2025-14237 |
|---|---|---|---|---|---|---|---|---|---|
| i-SENSYS MF752Cdw** | Main Controller v07.04 and earlier | Main Controller v08.01and higher | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ |
| i-SENSYS MF754Cdw II* | Main Controller v02.01 and earlier | Main Controller v02.02and higher | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ |
| i-SENSYS MF754Cdw** | Main Controller v07.04 and earlier | Main Controller v08.01and higher | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ |
| i-SENSYS X 1238i II | Main Controller v06.02 and earlier | Main Controller v07.01 and higher | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ |
| i-SENSYS X 1238iF II | Main Controller v06.02 and earlier | Main Controller v07.01 and higher | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ |
| i-SENSYS X 1238P II | Main Controller v06.02 and earlier | Main Controller v07.01 and higher | ✓ | ✓ | ✓ | ✓ | ✓ |  | ✓ |
| i-SENSYS X 1238Pr II | Main Controller v06.02 and earlier | Main Controller v07.01 and higher | ✓ | ✓ | ✓ | ✓ | ✓ |  | ✓ |
| i-SENSYS X 1440i** | Main Controller v07.01 and earlier | Main Controller v07.02and higher | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ |
| i-SENSYS X 1440iF** | Main Controller v07.01 and earlier | Main Controller v07.02and higher | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ |
| i-SENSYS X 1440P** | Main Controller v07.01 and earlier | Main Controller v07.02and higher | ✓ | ✓ | ✓ | ✓ | ✓ |  | ✓ |

| Products | Affected Firmware Version | Fix Firmware Version | CVE-2025-14231 | CVE-2025-14232 | CVE-2025-14233 | CVE-2025-14234 | CVE-2025-14235 | CVE-2025-14236 | CVE-2025-14237 |
|---|---|---|---|---|---|---|---|---|---|
| i-SENSYS X 1440Pr** | Main Controller v07.01 and earlier | Main Controller v07.02and higher | ✓ | ✓ | ✓ | ✓ | ✓ | | ✓ |
| i-SENSYS X C1333i** | Main Controller v07.04 and earlier | Main Controller v08.01and higher | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ |
| i-SENSYS X C1333iF** | Main Controller v07.04 and earlier | Main Controller v08.01and higher | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ |
| i-SENSYS X C1333P** | Main Controller v07.04 and earlier | Main Controller v08.01and higher | ✓ | ✓ | ✓ | ✓ | ✓ | | ✓ |