

## **CP2023-003 Vulnerability Mitigation/Remediation for Inkjet Printers (Home and Office/Large Format)**

July 31, 2023

Canon Inc.

### **Affected Inkjet Printers, Business Inkjet Printers**

E300 series

E3100 series

E3300 series

E3400 series

E4200 series

E460 series

E470 series

E480 series

E560 series

G3000 series

G3010 series

G3020 series

G3030 series

G3060 series

G3070 series

G3830

G3870

G4000 series

G4010 series

G4070 series

G4870

G500 series

G5000 series

G5080

G600 series

G6000 series

G6080

G7000 series

G7080

GM4000 series  
GM4080  
GX3000 series  
GX3080  
GX4000 series  
GX4080  
GX5000 series  
GX5080  
GX6000 series  
GX6080  
GX7000 series  
GX7080  
iB4000 series  
iB4100 series  
iP110  
MB2000 series  
MB2100 series  
MB2300 series  
MB2700 series  
MB5000 series  
MB5100 series  
MB5300 series  
MB5400 series  
MG2900 series  
MG3000 series  
MG3600 series  
MG5600 series  
MG5700 series  
MG6600 series  
MG6730  
MG6800 series  
MG6930  
MG7500 series  
MG7700 series  
MX470 series  
MX490 series

MX530 series  
PRO-10  
PRO-10S  
PRO-100  
PRO-100S  
PRO-1000  
PRO-200(CN)  
PRO-300(CN)  
PRO-500  
PRO-G1/PRO-300  
PRO-S1/PRO-200  
TR150 series  
TR150(CN)  
TR4500 series  
TR4600 series  
TR4700/TR4750i/TR4751i  
TR7000/TS7400series  
TR7000a series  
TR703  
TR7500 series  
TR7600a series  
TR8500 series  
TR8580  
TR8530  
TR8600 series  
TR8600a series  
TR8630  
TR8630a series  
TR9530  
TS300 series  
TS3100 series  
TS3300 series  
TS3400 series  
TS3500 series  
TS3720/TS3022/TS3730/TS3750i/TS3751i  
TS5000 series

TS5100 series  
TS5300 series  
TS5380  
TS6000 series  
TS6100 series  
TS6130  
TS6180  
TS6200 series  
TS6230  
TS6280  
TS6300 series  
TS6330  
TS6380  
TS700 series  
TS708 series  
TS7330  
TS7430  
TS7450i series  
TS7530  
TS8000 series  
TS8100/XK50series  
TS8130  
TS8180  
TS8230  
TS8280  
TS8330  
TS8380  
TS8430  
TS8530  
TS8630  
TS9000 series  
TS9100 series  
TS9180  
TS9500 series  
TS9580  
XK100

XK110

XK500

XK60/TS8300series

XK80/TS8200series

XK90

## Affected Large-Format Inkjet Printers

\*Printer models to use Reset LAN settings

PRO-520 \*  
PRO-521 \*  
PRO-540 \*  
PRO-540S \*  
PRO-541 \*  
PRO-541S \*  
PRO-560 \*  
PRO-560S \*  
PRO-561 \*  
PRO-561S \*  
PRO-2000 \*  
PRO-2100 \*  
PRO-4000 \*  
PRO-4000S \*  
PRO-4100 \*  
PRO-4100S \*  
PRO-6000 \*  
PRO-6000S \*  
PRO-6100 \*  
PRO-6100S \*  
TM-200 \*  
TM-205 \*  
TM-300 \*  
TM-305 \*  
TM-5200 \*  
TM-5205 \*  
TM-5300 \*  
TM-5305 \*  
TX-2000 \*  
TX-2100 \*  
TX-3000 \*  
TX-3100 \*  
TX-4000 \*

TX-4100 \*  
TX-5200 \*  
TX-5210 \*  
TX-5300 \*  
TX-5310 \*  
TX-5400 \*  
TX-5410 \*  
TZ-5300 \*  
TZ-30000 \*  
GP-200 \*  
GP-300 \*  
GP-520 \*  
GP-540 \*  
GP-5200 \*  
GP-5300 \*  
GP-2000 \*  
GP-4000 \*  
TC-20 \*  
TC-20M \*  
TC-5200 \*  
TC-5200M \*