

CPE2026-002 – Vulnerability Remediation for IJ Scan Utility for Windows – 26 February 2026

Affected Products/Models

Products	CVE-2026-1585	Fixed in MP Driver
MAXIFY MB2140	✓	m68n-win-mb2100-1_04-ea34_2.exe
MAXIFY MB2150	✓	m68n-win-mb2100-1_04-ea34_2.exe
MAXIFY MB2155	✓	m68n-win-mb2100-1_04-ea34_2.exe
MAXIFY MB2740	✓	m68n-win-mb2700-1_04-ea34_2.exe
MAXIFY MB2750	✓	m68n-win-mb2700-1_04-ea34_2.exe
MAXIFY MB2755	✓	m68n-win-mb2700-1_04-ea34_2.exe
MAXIFY MB5140	✓	m68n-win-mb5100-1_05-ea34_2.exe
MAXIFY MB5150	✓	m68n-win-mb5100-1_05-ea34_2.exe
MAXIFY MB5155	✓	m68n-win-mb5100-1_05-ea34_2.exe
MAXIFY MB5440	✓	m68n-win-mb5400-1_05-ea34_2.exe
MAXIFY MB5450	✓	m68n-win-mb5400-1_05-ea34_2.exe
MAXIFY MB5455	✓	m68n-win-mb5400-1_05-ea34_2.exe
PIXMA E3140	✓	mpnp-win-e3100-1_02-ea34_2.exe
PIXMA E3340	✓	md__win-e3300-1_02-ea34_2.exe
PIXMA E414	✓	mp68-win-e410-1_04-ea34_2.exe
PIXMA E4240	✓	md__win-e4200-1_02-ea34_2.exe
PIXMA E474	✓	mp68-win-e470-1_05-ea34_2.exe
PIXMA G2400	✓	mp68-win-g2000-1_04-ea34_2.exe
PIXMA G2410	✓	mpp__win-g2010-1_04-ea34_2.exe
PIXMA G2411	✓	mpp__win-g2010-1_04-ea34_2.exe
PIXMA G2415	✓	mpp__win-g2010-1_04-ea34_2.exe
PIXMA G2500	✓	mp68-win-g2000-1_04-ea34_2.exe
PIXMA G2501	✓	mp68-win-g2000-1_04-ea34_2.exe
PIXMA G2510	✓	mpp__win-g2010-1_04-ea34_2.exe
PIXMA G3400	✓	mp68-win-g3000-1_04-ea34_2.exe
PIXMA G3410	✓	mpp__win-g3010-1_04-ea34_2.exe
PIXMA G3411	✓	mpp__win-g3010-1_04-ea34_2.exe
PIXMA G3415	✓	mpp__win-g3010-1_04-ea34_2.exe
PIXMA G3500	✓	mp68-win-g3000-1_04-ea34_2.exe
PIXMA G3501	✓	mp68-win-g3000-1_04-ea34_2.exe
PIXMA G3510	✓	mpp__win-g3010-1_04-ea34_2.exe
PIXMA G3515	✓	mpp__win-g3010-1_04-ea34_2.exe
PIXMA G4400	✓	m68n-win-g4000-1_02-ea34_2.exe
PIXMA G4410	✓	mpnp-win-g4010-1_03-ea34_2.exe
PIXMA G4411	✓	mpnp-win-g4010-1_03-ea34_2.exe
PIXMA G4500	✓	m68n-win-g4000-1_02-ea34_2.exe

Products	CVE-2026-1585	Fixed in MP Driver
PIXMA G4510	✓	mpnp-win-g4010-1_03-ea34_2.exe
PIXMA G4511	✓	mpnp-win-g4010-1_03-ea34_2.exe
PIXMA G6040	✓	md__-win-g6000-1_02-ea34_2.exe
PIXMA G6050	✓	md__-win-g6000-1_02-ea34_2.exe
PIXMA G7040	✓	md__-win-g7000-1_01-ea34_2.exe
PIXMA G7050	✓	md__-win-g7000-1_01-ea34_2.exe
PIXMA GM4040	✓	md__-win-gm4000-1_02-ea34_2.exe
PIXMA GM4050	✓	md__-win-gm4000-1_02-ea34_2.exe
PIXMA MB3050	✓	mp68-win-mg3000-1_05-ea34_2.exe
PIXMA MG3040	✓	mp68-win-mg3000-1_05-ea34_2.exe
PIXMA MG3051	✓	mp68-win-mg3000-1_05-ea34_2.exe
PIXMA MG3052	✓	mp68-win-mg3000-1_05-ea34_2.exe
PIXMA MG3053	✓	mp68-win-mg3000-1_05-ea34_2.exe
PIXMA MG3640	✓	m68n-win-mg3600-1_04-ea34_2.exe
PIXMA MG3640S	✓	m68n-win-mg3600-1_04-ea34_2.exe
PIXMA MG3650	✓	m68n-win-mg3600-1_04-ea34_2.exe
PIXMA MG3650S	✓	m68n-win-mg3600-1_04-ea34_2.exe
PIXMA MG56851	✓	m68n-win-mg6800-1_01-ea34_2.exe
PIXMA MG5740	✓	m68n-win-mg5700-1_02-ea34_2.exe
PIXMA MG5750	✓	m68n-win-mg5700-1_02-ea34_2.exe
PIXMA MG5751	✓	m68n-win-mg5700-1_02-ea34_2.exe
PIXMA MG5752	✓	m68n-win-mg5700-1_02-ea34_2.exe
PIXMA MG5753	✓	m68n-win-mg5700-1_02-ea34_2.exe
PIXMA MG6840	✓	m68n-win-mg6800-1_01-ea34_2.exe
PIXMA MG6850	✓	m68n-win-mg6800-1_01-ea34_2.exe
PIXMA MG6852	✓	m68n-win-mg6800-1_01-ea34_2.exe
PIXMA MG6853	✓	m68n-win-mg6800-1_01-ea34_2.exe
PIXMA MG7740	✓	m68n-win-mg7700-1_01-ea34_2.exe
PIXMA MG7750	✓	m68n-win-mg7700-1_01-ea34_2.exe
PIXMA MG7751	✓	m68n-win-mg7700-1_01-ea34_2.exe
PIXMA MG7752	✓	m68n-win-mg7700-1_01-ea34_2.exe
PIXMA MG7753	✓	m68n-win-mg7700-1_01-ea34_2.exe
PIXMA TR4540	✓	md__-win-tr4500-1_04-ea34_2.exe
PIXMA TR4550	✓	md__-win-tr4500-1_04-ea34_2.exe
PIXMA TR4551	✓	md__-win-tr4500-1_04-ea34_2.exe
PIXMA TR7540	✓	mpnp-win-tr7500-1_03-ea34_2.exe
PIXMA TR7550	✓	mpnp-win-tr7500-1_03-ea34_2.exe
PIXMA TR8540	✓	mpnp-win-tr8500-1_03-ea34_2.exe
PIXMA TR8550	✓	mpnp-win-tr8500-1_03-ea34_2.exe
PIXMA TS3140	✓	mpnp-win-ts3100-1_03-ea34_2.exe
PIXMA TS3150	✓	mpnp-win-ts3100-1_03-ea34_2.exe
PIXMA TS3151	✓	mpnp-win-ts3100-1_03-ea34_2.exe
PIXMA TS3340	✓	md__-win-ts3300-1_05-ea34_2.exe
PIXMA TS3350	✓	md__-win-ts3300-1_05-ea34_2.exe
PIXMA TS3351	✓	md__-win-ts3300-1_05-ea34_2.exe
PIXMA TS3352	✓	md__-win-ts3300-1_05-ea34_2.exe

Products	CVE-2026-1585	Fixed in MP Driver
PIXMA TS3355	✓	md__-win-ts3300-1_05-ea34_2.exe
PIXMA TS5040	✓	m68n-win-ts5000-1_04-ea34_2.exe
PIXMA TS5050	✓	m68n-win-ts5000-1_04-ea34_2.exe
PIXMA TS5051	✓	m68n-win-ts5000-1_04-ea34_2.exe
PIXMA TS5053	✓	m68n-win-ts5000-1_04-ea34_2.exe
PIXMA TS5055	✓	m68n-win-ts5000-1_04-ea34_2.exe
PIXMA TS5140	✓	mpnp-win-ts5100-1_03-ea34_2.exe
PIXMA TS5150	✓	mpnp-win-ts5100-1_03-ea34_2.exe
PIXMA TS5151	✓	mpnp-win-ts5100-1_03-ea34_2.exe
PIXMA TS5340	✓	md__-win-ts5300-1_07-ea34_2.exe
PIXMA TS5340a	✓	md__-win-ts5300-1_07-ea34_2.exe
PIXMA TS5350	✓	md__-win-ts5300-1_07-ea34_2.exe
PIXMA TS5350a	✓	md__-win-ts5300-1_07-ea34_2.exe
PIXMA TS5351	✓	md__-win-ts5300-1_07-ea34_2.exe
PIXMA TS5351a	✓	md__-win-ts5300-1_07-ea34_2.exe
PIXMA TS5352	✓	md__-win-ts5300-1_07-ea34_2.exe
PIXMA TS5352a	✓	md__-win-ts5300-1_07-ea34_2.exe
PIXMA TS5353	✓	md__-win-ts5300-1_07-ea34_2.exe
PIXMA TS5353a	✓	md__-win-ts5300-1_07-ea34_2.exe
PIXMA TS5355	✓	md__-win-ts5300-1_07-ea34_2.exe
PIXMA TS5355a	✓	md__-win-ts5300-1_07-ea34_2.exe
PIXMA TS6040	✓	m68n-win-ts6000-1_03-ea34_2.exe
PIXMA TS6050	✓	m68n-win-ts6000-1_03-ea34_2.exe
PIXMA TS6051	✓	m68n-win-ts6000-1_03-ea34_2.exe
PIXMA TS6052	✓	m68n-win-ts6000-1_03-ea34_2.exe
PIXMA TS6140	✓	mpnp-win-ts6100-1_03-ea34_2.exe
PIXMA TS6150	✓	mpnp-win-ts6100-1_03-ea34_2.exe
PIXMA TS6151	✓	mpnp-win-ts6100-1_03-ea34_2.exe
PIXMA TS6240	✓	md__-win-ts6200-1_03-ea34_2.exe
PIXMA TS6250	✓	md__-win-ts6200-1_03-ea34_2.exe
PIXMA TS6251	✓	md__-win-ts6200-1_03-ea34_2.exe
PIXMA TS6340	✓	md__-win-ts6300-1_04-ea34_2.exe
PIXMA TS6340a	✓	md__-win-ts6300-1_04-ea34_2.exe
PIXMA TS6350	✓	md__-win-ts6300-1_04-ea34_2.exe
PIXMA TS6350a	✓	md__-win-ts6300-1_04-ea34_2.exe
PIXMA TS6351	✓	md__-win-ts6300-1_04-ea34_2.exe
PIXMA TS6351a	✓	md__-win-ts6300-1_04-ea34_2.exe
PIXMA TS8040	✓	m68n-win-ts8000-1_03-ea34_2.exe
PIXMA TS8050	✓	m68n-win-ts8000-1_03-ea34_2.exe
PIXMA TS8051	✓	m68n-win-ts8000-1_03-ea34_2.exe
PIXMA TS8052	✓	m68n-win-ts8000-1_03-ea34_2.exe
PIXMA TS8053	✓	m68n-win-ts8000-1_03-ea34_2.exe
PIXMA TS8140	✓	mpnp-win-ts8100-1_03-ea34_2.exe
PIXMA TS8150	✓	mpnp-win-ts8100-1_03-ea34_2.exe
PIXMA TS8151	✓	mpnp-win-ts8100-1_03-ea34_2.exe
PIXMA TS8152	✓	mpnp-win-ts8100-1_03-ea34_2.exe

Products	CVE-2026-1585	Fixed in MP Driver
PIXMA TS8240	✓	md__-win-ts8200-1_05-ea34_2.exe
PIXMA TS8250	✓	md__-win-ts8200-1_05-ea34_2.exe
PIXMA TS8251	✓	md__-win-ts8200-1_05-ea34_2.exe
PIXMA TS8252	✓	md__-win-ts8200-1_05-ea34_2.exe
PIXMA TS8340	✓	md__-win-ts8300-1_04-ea34_2.exe
PIXMA TS8340a	✓	md__-win-ts8300-1_04-ea34_2.exe
PIXMA TS8350	✓	md__-win-ts8300-1_04-ea34_2.exe
PIXMA TS8350a	✓	md__-win-ts8300-1_04-ea34_2.exe
PIXMA TS8351	✓	md__-win-ts8300-1_04-ea34_2.exe
PIXMA TS8351a	✓	md__-win-ts8300-1_04-ea34_2.exe
PIXMA TS8352	✓	md__-win-ts8300-1_04-ea34_2.exe
PIXMA TS8352a	✓	md__-win-ts8300-1_04-ea34_2.exe
PIXMA TS9040	✓	m68n-win-ts9000-1_03-ea34_2.exe
PIXMA TS9050	✓	m68n-win-ts9000-1_03-ea34_2.exe
PIXMA TS9055	✓	m68n-win-ts9000-1_03-ea34_2.exe
PIXMA TS9140	✓	mpnp-win-ts9100-1_03-ea34_2.exe
PIXMA TS9150	✓	mpnp-win-ts9100-1_03-ea34_2.exe
PIXMA TS9155	✓	mpnp-win-ts9100-1_03-ea34_2.exe
PIXMA TS9540	✓	md__-win-ts9500-1_06-ea34_2.exe
PIXMA TS9540A	✓	md__-win-ts9500-1_06-ea34_2.exe
PIXMA TS9541C	✓	md__-win-ts9500-1_06-ea34_2.exe
PIXMA TS9550	✓	md__-win-ts9500-1_06-ea34_2.exe
PIXMA TS9550A	✓	md__-win-ts9500-1_06-ea34_2.exe
PIXMA TS9551C	✓	md__-win-ts9500-1_06-ea34_2.exe
PIXMA TS9551CA	✓	md__-win-ts9500-1_06-ea34_2.exe