

CPE2025-001 – Regarding vulnerabilities Mitigation/Remediation for Small Office Multifunction Printers and Laser Printers – 27 January 2025 (Updated: 20 February 2026)

Affected Products/Models

* Added on 21 February 2025

** Added on 22 May 2025

*** Added on 20 June 2025

**** Added on 20 February 2026

Products	For CVE-2024-12647/CVE-2024-12648/CVE-2024-12649					For CVE-2025-2146**		
	Affected Firmware Version	Fix Firmware Version	CVE-2024-12647	CVE-2024-12648	CVE-2024-12649	Affected Firmware Version	Fix Firmware Version	CVE-2025-2146
imageRUNNER 1643i II*	V05.06 and earlier	V05.07 and higher	✓	✓	✓	V05.07 and earlier	V05.10 and higher	✓
imageRUNNER 1643iF II*	V05.06 and earlier	V05.07 and higher	✓	✓	✓	V05.07 and earlier	V05.10 and higher	✓
i-SENSYS LBP233dw*	V05.06 and earlier	V05.07 and higher	✓	✓	✓	V05.07 and earlier	V05.10 and higher	✓
i-SENSYS LBP236dw*	V05.06 and earlier	V05.07 and higher	✓	✓	✓	V05.07 and earlier	V05.10 and higher	✓
i-SENSYS LBP246dw****	V04.07 and earlier	V05.03 and higher	✓	✓	✓	V04.07 and earlier	V05.03 and higher	✓
i-SENSYS LBP631Cw	V05.06 and earlier	V05.07 and higher	✓	✓	✓	V05.07 and earlier	V05.10 and higher	✓
i-SENSYS LBP633Cdw	V05.06 and earlier	V05.07 and higher	✓	✓	✓	V05.07 and earlier	V05.10 and higher	✓
i-SENSYS LBP673Cdw****	V07.01 and earlier	V07.04 and higher	✓	✓	✓	V07.01 and earlier	V07.04 and higher	✓
i-SENSYS MF453dw*	V05.06 and earlier	V05.07 and higher	✓	✓	✓	V05.07 and earlier	V05.10 and higher	✓
i-SENSYS MF455dw*	V05.06 and earlier	V05.07 and higher	✓	✓	✓	V05.07 and earlier	V05.10 and higher	✓
i-SENSYS MF461dw****	V04.07 and earlier	V05.03 and higher	✓	✓	✓	V04.07 and earlier	V05.03 and higher	✓
i-SENSYS MF463dw****	V04.07 and earlier	V05.03 and higher	✓	✓	✓	V04.07 and earlier	V05.03 and higher	✓
i-SENSYS MF465dw****	V04.07 and earlier	V05.03 and higher	✓	✓	✓	V04.07 and earlier	V05.03 and higher	✓

Products	For CVE-2024-12647/CVE-2024-12648/CVE-2024-12649					For CVE-2025-2146**		
	Affected Firmware Version	Fix Firmware Version	CVE-2024-12647	CVE-2024-12648	CVE-2024-12649	Affected Firmware Version	Fix Firmware Version	CVE-2025-2146
i-SENSYS MF552dw*	V05.06 and earlier	V05.07 and higher	✓	✓	✓	V05.07 and earlier	V05.10 and higher	✓
i-SENSYS MF553dw*	V05.06 and earlier	V05.07 and higher	✓	✓	✓	V05.07 and earlier	V05.10 and higher	✓
i-SENSYS MF651Cw	V05.06 and earlier	V05.07 and higher	✓	✓	✓	V05.07 and earlier	V05.10 and higher	✓
i-SENSYS MF655Cdw	V05.06 and earlier	V05.07 and higher	✓	✓	✓	V05.07 and earlier	V05.10 and higher	✓
i-SENSYS MF657Cdw	V05.06 and earlier	V05.07 and higher	✓	✓	✓	V05.07 and earlier	V05.10 and higher	✓
i-SENSYS MF752Cdw****	V07.01 and earlier	V07.04 and higher	✓	✓	✓	V07.01 and earlier	V07.04 and higher	✓
i-SENSYS MF754Cdw****	V07.01 and earlier	V07.04 and higher	✓	✓	✓	V07.01 and earlier	V07.04 and higher	✓
i-SENSYS X 1238i II*	V05.06 and earlier	V05.07 and higher	✓	✓	✓	V05.07 and earlier	V05.10 and higher	✓
i-SENSYS X 1238iF II*	V05.06 and earlier	V05.07 and higher	✓	✓	✓	V05.07 and earlier	V05.10 and higher	✓
i-SENSYS X 1238P II*	V05.06 and earlier	V05.07 and higher	✓	✓	✓	V05.07 and earlier	V05.10 and higher	✓
i-SENSYS X 1238Pr II*	V05.06 and earlier	V05.07 and higher	✓	✓	✓	V05.07 and earlier	V05.10 and higher	✓
i-SENSYS X 1440i***	V04.07 and earlier	V05.03 and higher	✓	✓	✓	V04.07 and earlier	V05.03 and higher	✓
i-SENSYS X 1440iF***	V04.07 and earlier	V05.03 and higher	✓	✓	✓	V04.07 and earlier	V05.03 and higher	✓
i-SENSYS X 1440P***	V04.07 and earlier	V05.03 and higher	✓	✓	✓	V04.07 and earlier	V05.03 and higher	✓
i-SENSYS X 1440Pr***	V04.07 and earlier	V05.03 and higher	✓	✓	✓	V04.07 and earlier	V05.03 and higher	✓
i-SENSYS X C1333i****	V07.01 and earlier	V07.04 and higher	✓	✓	✓	V07.01 and earlier	V07.04 and higher	✓
i-SENSYS X C1333iF****	V07.01 and earlier	V07.04 and higher	✓	✓	✓	V07.01 and earlier	V07.04 and higher	✓
i-SENSYS X C1333P****	V07.01 and earlier	V07.04 and higher	✓	✓	✓	V07.01 and earlier	V07.04 and higher	✓