

**CPE2025-004 Vulnerability Mitigation/Remediation for Production Printers, Office/Small Office Multifunction Printers and Laser Printers Printers – 19 May 2025**

**Affected Products/Models**

Products	Affected Firmware Version	Fix Firmware Version / Guidance	Vulnerability Type	
			CVE-2025-3078	CVE-2025-3079
imagePRESS C10000VP	All versions	Follow hardening guidance	✓	
imagePRESS C10010VP	All versions	Follow hardening guidance	✓	
imagePRESS C165	V45.44 and earlier	V47.09 and higher	✓	
imagePRESS C170	V45.44 and earlier	V47.09 and higher	✓	
imagePRESS C265	V15.47 and earlier	V17.09 and higher	✓	
imagePRESS C270	V15.47 and earlier	V17.09 and higher	✓	
imagePRESS C60	All versions	Follow hardening guidance	✓	
imagePRESS C600	All versions	Follow hardening guidance	✓	
imagePRESS C650	All versions	Follow hardening guidance	✓	
imagePRESS C650i	All versions	Follow hardening guidance	✓	
imagePRESS C700	All versions	Follow hardening guidance	✓	
imagePRESS C710	All versions	Follow hardening guidance	✓	
imagePRESS C750	All versions	Follow hardening guidance	✓	
imagePRESS C800	All versions	Follow hardening guidance	✓	
imagePRESS C8000VP	All versions	Follow hardening guidance	✓	
imagePRESS C810	All versions	Follow hardening guidance	✓	
imagePRESS C850	All versions	Follow hardening guidance	✓	
imagePRESS C9010VP	All versions	Follow hardening guidance	✓	
imagePRESS C910	All versions	Follow hardening guidance	✓	
imagePRESS V1000	V12.24 and earlier	V17.09 and higher	✓	
imagePRESS V700	V12.24 and earlier	V17.09 and higher	✓	
imagePRESS V800	V12.24 and earlier	V17.09 and higher	✓	
imagePRESS V900	V12.24 and earlier	V17.09 and higher	✓	

Products	Affected Firmware Version	Fix Firmware Version / Guidance	Vulnerability Type	
			CVE-2025-3078	CVE-2025-3079
imageRUNNER 1133	All versions	Follow hardening guidance		✓
imageRUNNER 1133iF	All versions	Follow hardening guidance		✓
imageRUNNER 1435	All versions	Follow hardening guidance	✓	
imageRUNNER 1435i	All versions	Follow hardening guidance	✓	
imageRUNNER 1435iF	All versions	Follow hardening guidance	✓	
imageRUNNER 1435P	All versions	Follow hardening	✓	
imageRUNNER 1643i II	All versions	Follow hardening guidance		✓
imageRUNNER 2224	All versions	Follow hardening guidance	✓	
imageRUNNER 2224iF	All versions	Follow hardening guidance	✓	
imageRUNNER 2224N	All versions	Follow hardening guidance	✓	
imageRUNNER 2425	All versions	Follow hardening guidance	✓	
imageRUNNER 2425i	All versions	Follow hardening guidance	✓	
imageRUNNER 2625i	All versions	Follow hardening guidance	✓	
imageRUNNER 2630i	All versions	Follow hardening guidance	✓	
imageRUNNER 2635i	All versions	Follow hardening guidance	✓	
imageRUNNER 2645i	All versions	Follow hardening guidance	✓	
imageRUNNER 2725i	All versions	Follow hardening guidance	✓	
imageRUNNER 2730i	All versions	Follow hardening guidance	✓	
imageRUNNER 2745i	All versions	Follow hardening guidance	✓	
imageRUNNER 2925i	V6.01 and earlier	V7.09 and higher	✓	
imageRUNNER 2930i	V6.01 and earlier	V7.09 and higher	✓	
imageRUNNER 2945i	V6.01 and earlier	V7.09 and higher	✓	
imageRUNNER ADVANCE 3320	All versions	Follow hardening guidance	✓	
imageRUNNER ADVANCE 400i	All versions	Follow hardening guidance	✓	
imageRUNNER ADVANCE 4025i	All versions	Follow hardening guidance	✓	

Products	Affected Firmware Version	Fix Firmware Version / Guidance	Vulnerability Type	
			CVE-2025-3078	CVE-2025-3079
imageRUNNER ADVANCE 4035i	All versions	Follow hardening guidance	✓	
imageRUNNER ADVANCE 4045i	All versions	Follow hardening guidance	✓	
imageRUNNER ADVANCE 4051i	All versions	Follow hardening guidance	✓	
imageRUNNER ADVANCE 4225i	All versions	Follow hardening guidance	✓	
imageRUNNER ADVANCE 4235i	All versions	Follow hardening guidance	✓	
imageRUNNER ADVANCE 4245i	All versions	Follow hardening guidance	✓	
imageRUNNER ADVANCE 4251i	All versions	Follow hardening guidance	✓	
imageRUNNER ADVANCE 4525i	V75.44 and earlier	V77.09 and higher	✓	
imageRUNNER ADVANCE 4525i III	V45.44 and earlier	V47.09 and higher	✓	
imageRUNNER ADVANCE 4535i	V75.44 and earlier	V77.09 and higher	✓	
imageRUNNER ADVANCE 4535i III	V45.44 and earlier	V47.09 and higher	✓	
imageRUNNER ADVANCE 4545i	V75.44 and earlier	V77.09 and higher	✓	
imageRUNNER ADVANCE 4545i III	V45.44 and earlier	V47.09 and higher	✓	
imageRUNNER ADVANCE 4551i	V75.44 and earlier	V77.09 and higher	✓	
imageRUNNER ADVANCE 4551i III	V45.44 and earlier	V47.09 and higher	✓	
imageRUNNER ADVANCE 500i	All versions	Follow hardening guidance	✓	
imageRUNNER ADVANCE 5235i	All versions	Follow hardening guidance	✓	
imageRUNNER ADVANCE 5240i	All versions	Follow hardening guidance	✓	
imageRUNNER ADVANCE 525i	V75.44 and earlier	V77.09 and higher	✓	
imageRUNNER ADVANCE 525i III	V45.44 and earlier	V47.09 and higher	✓	
imageRUNNER ADVANCE 525iZ	V75.44 and earlier	V77.09 and higher	✓	
imageRUNNER ADVANCE 525iZ III	V45.44 and earlier	V47.09 and higher	✓	
imageRUNNER ADVANCE 5535	V75.44 and earlier	V77.09 and higher	✓	
imageRUNNER ADVANCE 5535i	V75.44 and earlier	V77.09 and higher	✓	
imageRUNNER ADVANCE 5540i	V75.44 and earlier	V77.09 and higher	✓	
imageRUNNER ADVANCE 6055	All versions	Follow hardening guidance	✓	
imageRUNNER ADVANCE 6055i	All versions	Follow hardening guidance	✓	
imageRUNNER ADVANCE 6065	All versions	Follow hardening guidance	✓	
imageRUNNER ADVANCE 6065i	All versions	Follow hardening guidance	✓	

Products	Affected Firmware Version	Fix Firmware Version / Guidance	Vulnerability Type	
			CVE-2025-3078	CVE-2025-3079
imageRUNNER ADVANCE 6075	All versions	Follow hardening guidance	✓	
imageRUNNER ADVANCE 6075i	All versions	Follow hardening guidance	✓	
imageRUNNER ADVANCE 615i	V75.44 and earlier	V77.09 and higher	✓	
imageRUNNER ADVANCE 615i III	V45.44 and earlier	V47.09 and higher	✓	
imageRUNNER ADVANCE 615iZ	V75.44 and earlier	V77.09 and higher	✓	
imageRUNNER ADVANCE 615iZ III	V45.44 and earlier	V47.09 and higher	✓	
imageRUNNER ADVANCE 6255i	All versions	Follow hardening guidance	✓	
imageRUNNER ADVANCE 6265i	All versions	Follow hardening guidance	✓	
imageRUNNER ADVANCE 6275i	All versions	Follow hardening guidance	✓	
imageRUNNER ADVANCE 6555i	V75.44 and earlier	V77.09 and higher	✓	
imageRUNNER ADVANCE 6555i III	V45.44 and earlier	V47.09 and higher	✓	
imageRUNNER ADVANCE 6565i	V75.44 and earlier	V77.09 and higher	✓	
imageRUNNER ADVANCE 6565i III	V45.44 and earlier	V47.09 and higher	✓	
imageRUNNER ADVANCE 6575i	V75.44 and earlier	V77.09 and higher	✓	
imageRUNNER ADVANCE 6575i III	V45.44 and earlier	V47.09 and higher	✓	
imageRUNNER ADVANCE 7055i	All versions	Follow hardening guidance	✓	
imageRUNNER ADVANCE 715i	V75.44 and earlier	V77.09 and higher	✓	
imageRUNNER ADVANCE 715i III	V45.44 and earlier	V47.09 and higher	✓	
imageRUNNER ADVANCE 715iZ	V75.44 and earlier	V77.09 and higher	✓	
imageRUNNER ADVANCE 715iZ III	V45.44 and earlier	V47.09 and higher	✓	
imageRUNNER ADVANCE 7260i	All versions	Follow hardening guidance	✓	
imageRUNNER ADVANCE 7270i	All versions	Follow hardening guidance	✓	
imageRUNNER ADVANCE 7280i	All versions	Follow hardening guidance	✓	
imageRUNNER ADVANCE 8085	All versions	Follow hardening guidance	✓	
imageRUNNER ADVANCE 8095	All versions	Follow hardening guidance	✓	
imageRUNNER ADVANCE 8105	All versions	Follow hardening guidance	✓	
imageRUNNER ADVANCE 8205	All versions	Follow hardening guidance	✓	
imageRUNNER ADVANCE 8285	All versions	Follow hardening guidance	✓	
imageRUNNER ADVANCE 8295	All versions	Follow hardening guidance	✓	

Products	Affected Firmware Version	Fix Firmware Version / Guidance	Vulnerability Type	
			CVE-2025-3078	CVE-2025-3079
imageRUNNER ADVANCE 8505	V75.44 and earlier	V77.09 and higher	✓	
imageRUNNER ADVANCE 8505 III	V45.44 and earlier	V47.09 and higher	✓	
imageRUNNER ADVANCE 8585	V75.44 and earlier	V77.09 and higher	✓	
imageRUNNER ADVANCE 8585 III	V45.44 and earlier	V47.09 and higher	✓	
imageRUNNER ADVANCE 8595	V75.44 and earlier	V77.09 and higher	✓	
imageRUNNER ADVANCE 8595 III	V45.44 and earlier	V47.09 and higher	✓	
imageRUNNER ADVANCE C2020i	All versions	Follow hardening guidance	✓	
imageRUNNER ADVANCE C2020L	All versions	Follow hardening guidance	✓	
imageRUNNER ADVANCE C2025i	All versions	Follow hardening guidance	✓	
imageRUNNER ADVANCE C2030i	All versions	Follow hardening guidance	✓	
imageRUNNER ADVANCE C2030L	All versions	Follow hardening guidance	✓	
imageRUNNER ADVANCE C2220i	All versions	Follow hardening guidance	✓	
imageRUNNER ADVANCE C2220L	All versions	Follow hardening guidance	✓	
imageRUNNER ADVANCE C2225i	All versions	Follow hardening guidance	✓	
imageRUNNER ADVANCE C2230i	All versions	Follow hardening guidance	✓	
imageRUNNER ADVANCE C250i	All versions	Follow hardening guidance	✓	
imageRUNNER ADVANCE C255i	V75.44 and earlier	V77.09 and higher	✓	
imageRUNNER ADVANCE C256i	V75.44 and earlier	V77.09 and higher	✓	
imageRUNNER ADVANCE C256i III	V45.44 and earlier	V47.09 and higher	✓	
imageRUNNER ADVANCE C3320i	All versions	Follow hardening guidance	✓	
imageRUNNER ADVANCE C3325i	All versions	Follow hardening guidance	✓	
imageRUNNER ADVANCE C3330i	All versions	Follow hardening guidance	✓	
imageRUNNER ADVANCE C350i	All versions	Follow hardening guidance	✓	
imageRUNNER ADVANCE C350P	All versions	Follow hardening guidance	✓	
imageRUNNER ADVANCE C351iF	All versions	Follow hardening guidance	✓	
imageRUNNER ADVANCE C3520i	V75.44 and earlier	V77.09 and higher	✓	
imageRUNNER ADVANCE C3520i III	V45.44 and earlier	V47.09 and higher	✓	
imageRUNNER ADVANCE C3525i	V75.44 and earlier	V77.09 and higher	✓	

Products	Affected Firmware Version	Fix Firmware Version / Guidance	Vulnerability Type	
			CVE-2025-3078	CVE-2025-3079
imageRUNNER ADVANCE C3525i III	V45.44 and earlier	V47.09 and higher	✓	
imageRUNNER ADVANCE C3530i	V75.44 and earlier	V77.09 and higher	✓	
imageRUNNER ADVANCE C3530i III	V45.44 and earlier	V47.09 and higher	✓	
imageRUNNER ADVANCE C355i	V75.44 and earlier	V77.09 and higher	✓	
imageRUNNER ADVANCE C355iFC	V75.44 and earlier	V77.09 and higher	✓	
imageRUNNER ADVANCE C355P	V75.44 and earlier	V77.09 and higher	✓	
imageRUNNER ADVANCE C356i	V75.44 and earlier	V77.09 and higher	✓	
imageRUNNER ADVANCE C356i III	V45.44 and earlier	V47.09 and higher	✓	
imageRUNNER ADVANCE C356P	V75.44 and earlier	V77.09 and higher	✓	
imageRUNNER ADVANCE C356P III	V45.44 and earlier	V47.09 and higher	✓	
imageRUNNER ADVANCE C475i III	V45.44 and earlier	V47.09 and higher	✓	
imageRUNNER ADVANCE C475iZ III	V45.44 and earlier	V47.09 and higher	✓	
imageRUNNER ADVANCE C478iZ	V25.47 and earlier	V27.09 and higher	✓	
imageRUNNER ADVANCE C5030i	All versions	Follow hardening guidance	✓	
imageRUNNER ADVANCE C5035i	All versions	Follow hardening guidance	✓	
imageRUNNER ADVANCE C5045i	All versions	Follow hardening guidance	✓	
imageRUNNER ADVANCE C5051i	All versions	Follow hardening guidance	✓	
imageRUNNER ADVANCE C5235	All versions	Follow hardening guidance	✓	
imageRUNNER ADVANCE C5240	All versions	Follow hardening guidance	✓	
imageRUNNER ADVANCE C5250	All versions	Follow hardening guidance	✓	
imageRUNNER ADVANCE C5250i	All versions	Follow hardening guidance	✓	
imageRUNNER ADVANCE C5255	All versions	Follow hardening guidance	✓	
imageRUNNER ADVANCE C5255i	All versions	Follow hardening guidance	✓	
imageRUNNER ADVANCE C5535i III	V45.44 and earlier	V47.09 and higher	✓	
imageRUNNER ADVANCE C5540i III	V45.44 and earlier	V47.09 and higher	✓	
imageRUNNER ADVANCE C5550i	V75.44 and earlier	V77.09 and higher	✓	
imageRUNNER ADVANCE C5550i III	V45.44 and earlier	V47.09 and higher	✓	
imageRUNNER ADVANCE C5560i	V75.44 and earlier	V77.09 and higher	✓	
imageRUNNER ADVANCE C5560i III	V45.44 and earlier	V47.09 and higher	✓	
imageRUNNER ADVANCE C7065i	All versions	Follow hardening guidance	✓	
imageRUNNER ADVANCE C7565i	V75.44 and earlier	V77.09 and higher	✓	
imageRUNNER ADVANCE C7565i III	V45.44 and earlier	V47.09 and higher	✓	

Products	Affected Firmware Version	Fix Firmware Version / Guidance	Vulnerability Type	
			CVE-2025-3078	CVE-2025-3079
imageRUNNER ADVANCE C7570i	V75.44 and earlier	V77.09 and higher	✓	
imageRUNNER ADVANCE C7570i III	V45.44 and earlier	V47.09 and higher	✓	
imageRUNNER ADVANCE C7580i	V75.44 and earlier	V77.09 and higher	✓	
imageRUNNER ADVANCE C7580i III	V45.44 and earlier	V47.09 and higher	✓	
imageRUNNER ADVANCE C9060	All versions	Follow hardening guidance	✓	
imageRUNNER ADVANCE C9070	All versions	Follow hardening guidance	✓	
imageRUNNER ADVANCE C9280	All versions	Follow hardening guidance	✓	
imageRUNNER ADVANCE DX 357P	V35.44 and earlier	V37.09 and higher	✓	
imageRUNNER ADVANCE DX 4725i	V35.44 and earlier	V37.09 and higher	✓	
imageRUNNER ADVANCE DX 4735i	V35.44 and earlier	V37.09 and higher	✓	
imageRUNNER ADVANCE DX 4745i	V35.44 and earlier	V37.09 and higher	✓	
imageRUNNER ADVANCE DX 4751i	V35.44 and earlier	V37.09 and higher	✓	
imageRUNNER ADVANCE DX 4825i	V25.49 and earlier	V27.09 and higher	✓	
imageRUNNER ADVANCE DX 4835i	V25.49 and earlier	V27.09 and higher	✓	
imageRUNNER ADVANCE DX 4845i	V25.49 and earlier	V27.09 and higher	✓	
imageRUNNER ADVANCE DX 4851i	V25.49 and earlier	V27.09 and higher	✓	
imageRUNNER ADVANCE DX 527iZ	V35.44 and earlier	V37.09 and higher	✓	
imageRUNNER ADVANCE DX 6000i	V35.44 and earlier	V37.09 and higher	✓	
imageRUNNER ADVANCE DX 617i	V35.44 and earlier	V37.09 and higher	✓	
imageRUNNER ADVANCE DX 617iZ	V35.44 and earlier	V37.09 and higher	✓	
imageRUNNER ADVANCE DX 6755i	V35.44 and earlier	V37.09 and higher	✓	
imageRUNNER ADVANCE DX 6765i	V35.44 and earlier	V37.09 and higher	✓	
imageRUNNER ADVANCE DX 6780i	V35.44 and earlier	V37.09 and higher	✓	
imageRUNNER ADVANCE DX 6860	V25.49 and earlier	V27.09 and higher	✓	
imageRUNNER ADVANCE DX 6860i	V25.49 and earlier	V27.09 and higher	✓	
imageRUNNER ADVANCE DX 6870	V25.49 and earlier	V27.09 and higher	✓	
imageRUNNER ADVANCE DX 6870i	V25.49 and earlier	V27.09 and higher	✓	
imageRUNNER ADVANCE DX 6980i	V5.47 and earlier	V7.09 and higher	✓	
imageRUNNER ADVANCE DX 717i	V35.44 and earlier	V37.09 and higher	✓	
imageRUNNER ADVANCE DX 717iZ	V35.44 and earlier	V37.09 and higher	✓	
imageRUNNER ADVANCE DX 8705	V35.44 and earlier	V37.09 and higher	✓	
imageRUNNER ADVANCE DX 8786	V35.44 and earlier	V37.09 and higher	✓	
imageRUNNER ADVANCE DX 8795	V35.44 and earlier	V37.09 and higher	✓	
imageRUNNER ADVANCE DX 8905	V5.47 and earlier	V7.09 and higher	✓	
imageRUNNER ADVANCE DX 8905P	V5.47 and earlier	V7.09 and higher	✓	
imageRUNNER ADVANCE DX C257i	V35.44 and earlier	V37.09 and higher	✓	
imageRUNNER ADVANCE DX C357i	V35.44 and earlier	V37.09 and higher	✓	
imageRUNNER ADVANCE DX C3720i	V35.44 and earlier	V37.09 and higher	✓	

Products	Affected Firmware Version	Fix Firmware Version / Guidance	Vulnerability Type	
			CVE-2025-3078	CVE-2025-3079
imageRUNNER ADVANCE DX C3725i	V35.44 and earlier	V37.09 and higher	✓	
imageRUNNER ADVANCE DX C3730i	V35.44 and earlier	V37.09 and higher	✓	
imageRUNNER ADVANCE DX C3822i	V25.47 and earlier	V27.09 and higher	✓	
imageRUNNER ADVANCE DX C3826i	V25.47 and earlier	V27.09 and higher	✓	
imageRUNNER ADVANCE DX C3830i	V25.47 and earlier	V27.09 and higher	✓	
imageRUNNER ADVANCE DX C3835i	V25.47 and earlier	V27.09 and higher	✓	
imageRUNNER ADVANCE DX C477i	V35.44 and earlier	V37.09 and higher	✓	
imageRUNNER ADVANCE DX C477iZ	V35.44 and earlier	V37.09 and higher	✓	
imageRUNNER ADVANCE DX C478i	V25.47 and earlier	V27.09 and higher	✓	
imageRUNNER ADVANCE DX C5735i	V35.44 and earlier	V37.09 and higher	✓	
imageRUNNER ADVANCE DX C5740i	V35.44 and earlier	V37.09 and higher	✓	
imageRUNNER ADVANCE DX C5750i	V35.44 and earlier	V37.09 and higher	✓	
imageRUNNER ADVANCE DX C5760i	V35.44 and earlier	V37.09 and higher	✓	
imageRUNNER ADVANCE DX C5840i	V25.49 and earlier	V27.09 and higher	✓	
imageRUNNER ADVANCE DX C5850i	V25.49 and earlier	V27.09 and higher	✓	
imageRUNNER ADVANCE DX C5860i	V25.49 and earlier	V27.09 and higher	✓	
imageRUNNER ADVANCE DX C5870i	V25.49 and earlier	V27.09 and higher	✓	
imageRUNNER ADVANCE DX C7765i	V35.44 and earlier	V37.09 and higher	✓	
imageRUNNER ADVANCE DX C7770i	V35.44 and earlier	V37.09 and higher	✓	
imageRUNNER ADVANCE DX C7780i	V35.44 and earlier	V37.09 and higher	✓	
imageRUNNER C1225	All versions	Follow hardening guidance		✓
imageRUNNER C1225iF	All versions	Follow hardening guidance		✓
imageRUNNER C1325iF	All versions	Follow hardening guidance	✓	
imageRUNNER C1335iF	All versions	Follow hardening guidance	✓	
imageRUNNER C1335iFC	All versions	Follow hardening guidance	✓	
imageRUNNER C1533iF	All versions	Follow hardening guidance	✓	
imageRUNNER C1538iF	All versions	Follow hardening guidance		✓
imageRUNNER C3025	All versions	Follow hardening guidance	✓	
imageRUNNER C3025i	All versions	Follow hardening guidance	✓	
imageRUNNER C3125i	All versions	Follow hardening guidance	✓	
imageRUNNER C3226i	All versions	Follow hardening guidance	✓	
imageRUNNER C3326i	V6.01 and earlier	V7.09 and higher	✓	

Products	Affected Firmware Version	Fix Firmware Version / Guidance	Vulnerability Type	
			CVE-2025-3078	CVE-2025-3079
i-SENSYS LBP212dw	All versions	Follow hardening guidance		✓
i-SENSYS LBP214dw	All versions	Follow hardening guidance		✓
i-SENSYS LBP215x	All versions	Follow hardening guidance		✓
i-SENSYS LBP226dw	All versions	Follow hardening guidance		✓
i-SENSYS LBP228x	All versions	Follow hardening guidance		✓
i-SENSYS LBP233dw	All versions	Follow hardening guidance		✓
i-SENSYS LBP236dw	All versions	Follow hardening guidance		✓
i-SENSYS LBP243dw	All versions	Follow hardening guidance		✓
i-SENSYS LBP246dw	All versions	Follow hardening guidance		✓
i-SENSYS LBP251dw	All versions	Follow hardening guidance		✓
i-SENSYS LBP252dw	All versions	Follow hardening guidance		✓
i-SENSYS LBP253x	All versions	Follow hardening guidance		✓
i-SENSYS LBP611Cn	All versions	Follow hardening guidance		✓
i-SENSYS LBP613Cdw	All versions	Follow hardening guidance		✓
i-SENSYS LBP621Cw	All versions	Follow hardening guidance		✓
i-SENSYS LBP623Cdw	All versions	Follow hardening guidance		✓
i-SENSYS LBP631Cw	All versions	Follow hardening guidance		✓
i-SENSYS LBP633Cdw	All versions	Follow hardening guidance		✓
i-SENSYS LBP653Cdw	All versions	Follow hardening guidance		✓
i-SENSYS LBP654Cx	All versions	Follow hardening guidance		✓
i-SENSYS LBP663Cdw	All versions	Follow hardening guidance		✓
i-SENSYS LBP664Cx	All versions	Follow hardening guidance		✓
i-SENSYS LBP722Cdw	All versions	Follow hardening guidance		✓

Products	Affected Firmware Version	Fix Firmware Version / Guidance	Vulnerability Type	
			CVE-2025-3078	CVE-2025-3079
i-SENSYS LBP732Cdw	V7.09 and earlier	V8.16 and higher		✓
i-SENSYS MF264dw II	All versions	Follow hardening guidance		✓
i-SENSYS MF267dw II	All versions	Follow hardening guidance		✓
i-SENSYS MF272dw	All versions	Follow hardening guidance		✓
i-SENSYS MF275dw	All versions	Follow hardening guidance		✓
i-SENSYS MF287dw	All versions	Follow hardening guidance		✓
i-SENSYS MF411dw	All versions	Follow hardening guidance		✓
i-SENSYS MF416dw	All versions	Follow hardening guidance		✓
i-SENSYS MF418x	All versions	Follow hardening guidance		✓
i-SENSYS MF419x	All versions	Follow hardening guidance		✓
i-SENSYS MF421dw	All versions	Follow hardening guidance		✓
i-SENSYS MF426dw	All versions	Follow hardening guidance		✓
i-SENSYS MF428x	All versions	Follow hardening guidance		✓
i-SENSYS MF429x	All versions	Follow hardening guidance		✓
i-SENSYS MF443dw	All versions	Follow hardening guidance		✓
i-SENSYS MF445dw	All versions	Follow hardening guidance		✓
i-SENSYS MF446x	All versions	Follow hardening guidance		✓
i-SENSYS MF449x	All versions	Follow hardening guidance		✓
i-SENSYS MF453dw	All versions	Follow hardening guidance		✓
i-SENSYS MF455dw	All versions	Follow hardening guidance		✓
i-SENSYS MF463dw	All versions	Follow hardening guidance		✓
i-SENSYS MF465dw	All versions	Follow hardening guidance		✓
i-SENSYS MF512x	All versions	Follow hardening guidance		✓

Products	Affected Firmware Version	Fix Firmware Version / Guidance	Vulnerability Type	
			CVE-2025-3078	CVE-2025-3079
i-SENSYS MF515x	All versions	Follow hardening guidance		✓
i-SENSYS MF522x	All versions	Follow hardening guidance		✓
i-SENSYS MF525x	All versions	Follow hardening guidance		✓
i-SENSYS MF552dw	All versions	Follow hardening guidance		✓
i-SENSYS MF553dw	All versions	Follow hardening guidance		✓
i-SENSYS MF5940dn	All versions	Follow hardening guidance		✓
i-SENSYS MF5980dw	All versions	Follow hardening guidance		✓
i-SENSYS MF6140dn	All versions	Follow hardening guidance		✓
i-SENSYS MF6180dw	All versions	Follow hardening guidance		✓
i-SENSYS MF623Cn	All versions	Follow hardening guidance		✓
i-SENSYS MF628Cw	All versions	Follow hardening guidance		✓
i-SENSYS MF631Cn	All versions	Follow hardening guidance		✓
i-SENSYS MF633Cdw	All versions	Follow hardening guidance		✓
i-SENSYS MF635Cx	All versions	Follow hardening guidance		✓
i-SENSYS MF641Cw	All versions	Follow hardening guidance		✓
i-SENSYS MF643Cdw	All versions	Follow hardening guidance		✓
i-SENSYS MF645Cx	All versions	Follow hardening guidance		✓
i-SENSYS MF651Cw	All versions	Follow hardening guidance		✓
i-SENSYS MF655Cdw	All versions	Follow hardening guidance		✓
i-SENSYS MF657Cdw	All versions	Follow hardening guidance		✓
i-SENSYS MF724Cdw	All versions	Follow hardening guidance		✓
i-SENSYS MF728Cdw	All versions	Follow hardening guidance		✓
i-SENSYS MF729Cx	All versions	Follow hardening guidance		✓

Products	Affected Firmware Version	Fix Firmware Version / Guidance	Vulnerability Type	
			CVE-2025-3078	CVE-2025-3079
i-SENSYS MF732Cdw	All versions	Follow hardening guidance		✓
i-SENSYS MF734Cdw	All versions	Follow hardening guidance		✓
i-SENSYS MF735Cx	All versions	Follow hardening guidance		✓
i-SENSYS MF752Cdw	All versions	Follow hardening guidance		✓
i-SENSYS MF754Cdw	All versions	Follow hardening guidance		✓
i-SENSYS MF832Cdw	All versions	Follow hardening guidance		✓
i-SENSYS MF8340	All versions	Follow hardening guidance		✓
i-SENSYS MF8360	All versions	Follow hardening guidance		✓
i-SENSYS MF8380	All versions	Follow hardening guidance		✓
i-SENSYS MF842Cdw	V6.03 and earlier	V8.16 and higher		✓
i-SENSYS X 1238i II	All versions	Follow hardening guidance		✓
i-SENSYS X 1238iF II	All versions	Follow hardening guidance		✓
i-SENSYS X 1238P II	All versions	Follow hardening guidance		✓
i-SENSYS X 1238Pr II	All versions	Follow hardening guidance		✓
i-SENSYS X 1440i	All versions	Follow hardening guidance		✓
i-SENSYS X 1440iF	All versions	Follow hardening guidance		✓
i-SENSYS X 1440P	All versions	Follow hardening guidance		✓
i-SENSYS X 1440Pr	All versions	Follow hardening guidance		✓
i-SENSYS X 1861P	All versions	Follow hardening guidance		✓
i-SENSYS X 1871P	All versions	Follow hardening guidance		✓
i-SENSYS X C1127P	All versions	Follow hardening guidance		✓
i-SENSYS X C1333i	All versions	Follow hardening guidance		✓
i-SENSYS X C1333iF	All versions	Follow hardening guidance		✓
i-SENSYS X C1533iF II	V6.03 and earlier	V8.16 and higher		✓

Products	Affected Firmware Version	Fix Firmware Version / Guidance	Vulnerability Type	
			CVE-2025-3078	CVE-2025-3079
i-SENSYS X C1533P	All versions	Follow hardening guidance		✓
i-SENSYS X C1533P II	V7.09 and earlier	V8.16 and higher		✓
i-SENSYS X C1538iF II	V6.03 and earlier	V8.16 and higher		✓
i-SENSYS X C1538P	All versions	Follow hardening guidance		✓
i-SENSYS X C1538P II	V7.09 and earlier	V8.16 and higher		✓
i-SENSYS X C1936P	All versions	Follow hardening guidance		✓
i-SENSYS X C1946P	All versions	Follow hardening guidance		✓
i-SENSYS X MF8230Cn	All versions	Follow hardening guidance		✓
i-SENSYS X MF8280Cw	All versions	Follow hardening guidance		✓
i-SENSYS X MF8540Cdn	All versions	Follow hardening guidance		✓
i-SENSYS X MF8550Cdn	All versions	Follow hardening guidance		✓
i-SENSYS X MF8580Cdw	All versions	Follow hardening guidance		✓