

## CPE2026-003 – Vulnerability Mitigation/Remediation for Production Printers and Office Multifunction Printers – 23 April 2026 (Updated: 29 June 2026)

### Affected Products/Models

\* Added on 29 June 2026

Products	Affected Firmware Version	Fix Firmware Version	CVE-2026-1789
imageFORCE 1643*	v1.01 or earlier	v1.03 or later	✓
imageFORCE 1643F*	v1.01 or earlier	v1.03 or later	✓
imageFORCE 520	v4.04 or earlier	v4.08 or later	✓
imageFORCE 520Z	v4.04 or earlier	v4.08 or later	✓
imageFORCE 610	v4.04 or earlier	v4.08 or later	✓
imageFORCE 610Z	v4.04 or earlier	v4.08 or later	✓
imageFORCE 6155	v9.04 or earlier	v9.08 or later	✓
imageFORCE 6160	v9.04 or earlier	v9.08 or later	✓
imageFORCE 6170	v9.04 or earlier	v9.08 or later	✓
imageFORCE 710	v4.04 or earlier	v4.08 or later	✓
imageFORCE 710Z	v4.04 or earlier	v4.08 or later	✓
imageFORCE 8105	v4.04 or earlier	v4.08 or later	✓
imageFORCE 8105P	v4.04 or earlier	v4.08 or later	✓
imageFORCE 8186	v4.04 or earlier	v4.08 or later	✓
imageFORCE 8186P	v4.04 or earlier	v4.08 or later	✓
imageFORCE 8195	v4.04 or earlier	v4.08 or later	✓
imageFORCE 8195P	v4.04 or earlier	v4.08 or later	✓
imageFORCE C3150	v4.04 or earlier	v4.08 or later	✓
imageFORCE C331	v4.04 or earlier	v4.08 or later	✓
imageFORCE C331Z	v4.04 or earlier	v4.08 or later	✓
imageFORCE C431	v4.04 or earlier	v4.08 or later	✓
imageFORCE C431Z	v4.04 or earlier	v4.08 or later	✓
imageFORCE C5140	v9.04 or earlier	v9.08 or later	✓
imageFORCE C5150	v9.04 or earlier	v9.08 or later	✓
imageFORCE C5160	v9.04 or earlier	v9.08 or later	✓
imageFORCE C5170	v9.04 or earlier	v9.08 or later	✓
imageFORCE C521	v4.04 or earlier	v4.08 or later	✓
imageFORCE C521Z	v4.04 or earlier	v4.08 or later	✓

Products	Affected Firmware Version	Fix Firmware Version	CVE-2026-1789
imageFORCE C611	v4.04 or earlier	v4.08 or later	✓
imageFORCE C611Z	v4.04 or earlier	v4.08 or later	✓
imageFORCE C7165	v9.04 or earlier	v9.08 or later	✓
imagePRESS C165	v53.04 or earlier	v53.06 or later	✓
imagePRESS C170	v53.04 or earlier	v53.06 or later	✓
imagePRESS C265	v26.04 or earlier	v26.06 or later	✓
imagePRESS C270	v26.04 or earlier	v26.06 or later	✓
imagePRESS V1000	v25.15 or earlier	v25.28 or later	✓
imagePRESS V700	v25.15 or earlier	v25.28 or later	✓
imagePRESS V800	v25.15 or earlier	v25.28 or later	✓
imagePRESS V900	v25.15 or earlier	v25.28 or later	✓
imageRUNNER 2425	v15.00 or earlier	v15.10 or later	✓
imageRUNNER 2425 II	v3.22 or earlier	v4.06 or later	✓
imageRUNNER 2425i	v15.00 or earlier	v15.10 or later	✓
imageRUNNER 2625i	v15.00 or earlier	v15.10 or later	✓
imageRUNNER 2630i	v15.00 or earlier	v15.10 or later	✓
imageRUNNER 2645i	v15.00 or earlier	v15.10 or later	✓
imageRUNNER 2725i	v8.12 or earlier	v10.20 or later	✓
imageRUNNER 2730i	v8.12 or earlier	v10.20 or later	✓
imageRUNNER 2745i	v8.12 or earlier	v10.20 or later	✓
imageRUNNER 2925i	v16.04 or earlier	v16.06 or later	✓
imageRUNNER 2930i	v16.04 or earlier	v16.06 or later	✓
imageRUNNER 2945i	v16.04 or earlier	v16.06 or later	✓
imageRUNNER ADVANCE 4525i	v81.25 or earlier	v81.43 or later	✓
imageRUNNER ADVANCE 4525i II	v81.25 or earlier	v81.43 or later	✓
imageRUNNER ADVANCE 4525i III	v51.25 or earlier	v51.43 or later	✓
imageRUNNER ADVANCE 4535i	v81.25 or earlier	v81.43 or later	✓
imageRUNNER ADVANCE 4535i II	v81.25 or earlier	v81.43 or later	✓
imageRUNNER ADVANCE 4535i III	v51.25 or earlier	v51.43 or later	✓
imageRUNNER ADVANCE 4545i	v81.25 or earlier	v81.43 or later	✓
imageRUNNER ADVANCE 4545i II	v81.25 or earlier	v81.43 or later	✓
imageRUNNER ADVANCE 4545i III	v51.25 or earlier	v51.43 or later	✓

Products	Affected Firmware Version	Fix Firmware Version	CVE-2026-1789
imageRUNNER ADVANCE 4551i	v81.25 or earlier	v81.43 or later	✓
imageRUNNER ADVANCE 4551i II	v81.25 or earlier	v81.43 or later	✓
imageRUNNER ADVANCE 525i II	v81.25 or earlier	v81.43 or later	✓
imageRUNNER ADVANCE 525i III	v51.25 or earlier	v51.43 or later	✓
imageRUNNER ADVANCE 525iZ II	v81.25 or earlier	v81.43 or later	✓
imageRUNNER ADVANCE 525iZ III	v51.25 or earlier	v51.43 or later	✓
imageRUNNER ADVANCE 615i II	v81.25 or earlier	v81.43 or later	✓
imageRUNNER ADVANCE 615i III	v51.25 or earlier	v51.43 or later	✓
imageRUNNER ADVANCE 615iZ II	v81.25 or earlier	v81.43 or later	✓
imageRUNNER ADVANCE 615iZ III	v51.25 or earlier	v51.43 or later	✓
imageRUNNER ADVANCE 6555i	v81.25 or earlier	v81.43 or later	✓
imageRUNNER ADVANCE 6555i II	v81.25 or earlier	v81.43 or later	✓
imageRUNNER ADVANCE 6555i III	v51.25 or earlier	v51.43 or later	✓
imageRUNNER ADVANCE 6565i	v81.25 or earlier	v81.43 or later	✓
imageRUNNER ADVANCE 6565i II	v81.25 or earlier	v81.43 or later	✓
imageRUNNER ADVANCE 6565i III	v51.25 or earlier	v51.43 or later	✓
imageRUNNER ADVANCE 6575i	v81.25 or earlier	v81.43 or later	✓
imageRUNNER ADVANCE 6575i II	v81.25 or earlier	v81.43 or later	✓
imageRUNNER ADVANCE 6575i III	v51.25 or earlier	v51.43 or later	✓
imageRUNNER ADVANCE 715i II	v81.25 or earlier	v81.43 or later	✓
imageRUNNER ADVANCE 715i III	v51.25 or earlier	v51.43 or later	✓
imageRUNNER ADVANCE 715iZ II	v81.25 or earlier	v81.43 or later	✓

<b>Products</b>	<b>Affected Firmware Version</b>	<b>Fix Firmware Version</b>	<b>CVE-2026-1789</b>
imageRUNNER ADVANCE 715iZ III	v51.25 or earlier	v51.43 or later	✓
imageRUNNER ADVANCE 8505	v81.25 or earlier	v81.43 or later	✓
imageRUNNER ADVANCE 8505	v81.25 or earlier	v81.43 or later	✓
imageRUNNER ADVANCE 8505 II	v81.25 or earlier	v81.43 or later	✓
imageRUNNER ADVANCE 8505 II	v81.25 or earlier	v81.43 or later	✓
imageRUNNER ADVANCE 8505 III	v51.25 or earlier	v51.43 or later	✓
imageRUNNER ADVANCE 8585	v81.25 or earlier	v81.43 or later	✓
imageRUNNER ADVANCE 8585	v81.25 or earlier	v81.43 or later	✓
imageRUNNER ADVANCE 8585 II	v81.25 or earlier	v81.43 or later	✓
imageRUNNER ADVANCE 8585 II	v81.25 or earlier	v81.43 or later	✓
imageRUNNER ADVANCE 8585 III	v51.25 or earlier	v51.43 or later	✓
imageRUNNER ADVANCE 8595	v81.25 or earlier	v81.43 or later	✓
imageRUNNER ADVANCE 8595	v81.25 or earlier	v81.43 or later	✓
imageRUNNER ADVANCE 8595 II	v81.25 or earlier	v81.43 or later	✓
imageRUNNER ADVANCE 8595 II	v81.25 or earlier	v81.43 or later	✓
imageRUNNER ADVANCE 8595 III	v51.25 or earlier	v51.43 or later	✓
imageRUNNER ADVANCE C255i	v81.25 or earlier	v81.43 or later	✓
imageRUNNER ADVANCE C256 III	v51.25 or earlier	v51.43 or later	✓
imageRUNNER ADVANCE C256i	v81.25 or earlier	v81.43 or later	✓
imageRUNNER ADVANCE C256i II	v81.25 or earlier	v81.43 or later	✓
imageRUNNER ADVANCE C256P II	v81.25 or earlier	v81.43 or later	✓
imageRUNNER ADVANCE C3520i	v81.25 or earlier	v81.43 or later	✓

<b>Products</b>	<b>Affected Firmware Version</b>	<b>Fix Firmware Version</b>	<b>CVE-2026-1789</b>
imageRUNNER ADVANCE C3520i II	v81.25 or earlier	v81.43 or later	✓
imageRUNNER ADVANCE C3520i III	v51.25 or earlier	v51.43 or later	✓
imageRUNNER ADVANCE C3525i	v81.25 or earlier	v81.43 or later	✓
imageRUNNER ADVANCE C3525i II	v81.25 or earlier	v81.43 or later	✓
imageRUNNER ADVANCE C3525i III	v51.25 or earlier	v51.43 or later	✓
imageRUNNER ADVANCE C3530i	v81.25 or earlier	v81.43 or later	✓
imageRUNNER ADVANCE C3530i II	v81.25 or earlier	v81.43 or later	✓
imageRUNNER ADVANCE C3530i III	v51.25 or earlier	v51.43 or later	✓
imageRUNNER ADVANCE C355i	v81.25 or earlier	v81.43 or later	✓
imageRUNNER ADVANCE C355iFC	v81.25 or earlier	v81.43 or later	✓
imageRUNNER ADVANCE C355P	v81.25 or earlier	v81.43 or later	✓
imageRUNNER ADVANCE C356 III	v51.25 or earlier	v51.43 or later	✓
imageRUNNER ADVANCE C356i	v81.25 or earlier	v81.43 or later	✓
imageRUNNER ADVANCE C356i II	v81.25 or earlier	v81.43 or later	✓
imageRUNNER ADVANCE C356P II	v81.25 or earlier	v81.43 or later	✓
imageRUNNER ADVANCE C356P III	v51.25 or earlier	v51.43 or later	✓
imageRUNNER ADVANCE C475i III	v51.25 or earlier	v51.43 or later	✓
imageRUNNER ADVANCE C475iZ III	v51.25 or earlier	v51.43 or later	✓
imageRUNNER ADVANCE C5535i	v81.25 or earlier	v81.43 or later	✓
imageRUNNER ADVANCE C5535i III	v51.25 or earlier	v51.43 or later	✓
imageRUNNER ADVANCE C5540i	v81.25 or earlier	v81.43 or later	✓
imageRUNNER ADVANCE C5540i III	v51.25 or earlier	v51.43 or later	✓

Products	Affected Firmware Version	Fix Firmware Version	CVE-2026-1789
imageRUNNER ADVANCE C5550i	v81.25 or earlier	v81.43 or later	✓
imageRUNNER ADVANCE C5550i III	v51.25 or earlier	v51.43 or later	✓
imageRUNNER ADVANCE C5560i	v81.25 or earlier	v81.43 or later	✓
imageRUNNER ADVANCE C5560i III	v51.25 or earlier	v51.43 or later	✓
imageRUNNER ADVANCE C7565i	v81.25 or earlier	v81.43 or later	✓
imageRUNNER ADVANCE C7565i II	v81.25 or earlier	v81.43 or later	✓
imageRUNNER ADVANCE C7565i III	v51.25 or earlier	v51.43 or later	✓
imageRUNNER ADVANCE C7570i	v81.25 or earlier	v81.43 or later	✓
imageRUNNER ADVANCE C7570i II	v81.25 or earlier	v81.43 or later	✓
imageRUNNER ADVANCE C7570i III	v51.25 or earlier	v51.43 or later	✓
imageRUNNER ADVANCE C7580i	v81.25 or earlier	v81.43 or later	✓
imageRUNNER ADVANCE C7580i II	v81.25 or earlier	v81.43 or later	✓
imageRUNNER ADVANCE C7580i III	v51.25 or earlier	v51.43 or later	✓
imageRUNNER ADVANCE DX 4725i	v43.04 or earlier	v43.06 or later	✓
imageRUNNER ADVANCE DX 4735i	v43.04 or earlier	v43.06 or later	✓
imageRUNNER ADVANCE DX 4745i	v43.04 or earlier	v43.06 or later	✓
imageRUNNER ADVANCE DX 4751i	v43.04 or earlier	v43.06 or later	✓
imageRUNNER ADVANCE DX 4825i	v26.04 or earlier	v26.08 or later	✓
imageRUNNER ADVANCE DX 4835i	v26.04 or earlier	v26.08 or later	✓
imageRUNNER ADVANCE DX 4845i	v26.04 or earlier	v26.08 or later	✓
imageRUNNER ADVANCE DX 4925i	v16.04 or earlier	v16.08 or later	✓
imageRUNNER ADVANCE DX 4935i	v16.04 or earlier	v16.08 or later	✓

Products	Affected Firmware Version	Fix Firmware Version	CVE-2026-1789
imageRUNNER ADVANCE DX 4945i	v16.04 or earlier	v16.08 or later	✓
imageRUNNER ADVANCE DX 527i	v43.04 or earlier	v43.06 or later	✓
imageRUNNER ADVANCE DX 527iZ	v43.04 or earlier	v43.06 or later	✓
imageRUNNER ADVANCE DX 529i	v16.04 or earlier	v16.06 or later	✓
imageRUNNER ADVANCE DX 529iZ	v16.04 or earlier	v16.06 or later	✓
imageRUNNER ADVANCE DX 6000i	v41.25 or earlier	v41.43 or later	✓
imageRUNNER ADVANCE DX 617i	v43.04 or earlier	v43.06 or later	✓
imageRUNNER ADVANCE DX 617iZ	v43.04 or earlier	v43.06 or later	✓
imageRUNNER ADVANCE DX 619i	v16.04 or earlier	v16.06 or later	✓
imageRUNNER ADVANCE DX 619iZ	v16.04 or earlier	v16.06 or later	✓
imageRUNNER ADVANCE DX 6755i	v43.04 or earlier	v43.06 or later	✓
imageRUNNER ADVANCE DX 6765i	v43.04 or earlier	v43.06 or later	✓
imageRUNNER ADVANCE DX 6780i	v43.04 or earlier	v43.06 or later	✓
imageRUNNER ADVANCE DX 6855i	v36.04 or earlier	v36.08 or later	✓
imageRUNNER ADVANCE DX 6860i	v36.04 or earlier	v36.08 or later	✓
imageRUNNER ADVANCE DX 6870i	v36.04 or earlier	v36.08 or later	✓
imageRUNNER ADVANCE DX 6980i	v16.04 or earlier	v16.06 or later	✓
imageRUNNER ADVANCE DX 717i	v43.04 or earlier	v43.06 or later	✓
imageRUNNER ADVANCE DX 717iZ	v43.04 or earlier	v43.06 or later	✓
imageRUNNER ADVANCE DX 719i	v16.04 or earlier	v16.06 or later	✓
imageRUNNER ADVANCE DX 719iZ	v16.04 or earlier	v16.06 or later	✓
imageRUNNER ADVANCE DX 8705	v43.04 or earlier	v43.06 or later	✓

<b>Products</b>	<b>Affected Firmware Version</b>	<b>Fix Firmware Version</b>	<b>CVE-2026-1789</b>
imageRUNNER ADVANCE DX 8786	v43.04 or earlier	v43.06 or later	✓
imageRUNNER ADVANCE DX 8795	v43.04 or earlier	v43.06 or later	✓
imageRUNNER ADVANCE DX 8905	v16.04 or earlier	v16.06 or later	✓
imageRUNNER ADVANCE DX 8986	v16.04 or earlier	v16.06 or later	✓
imageRUNNER ADVANCE DX 8995	v16.04 or earlier	v16.06 or later	✓
imageRUNNER ADVANCE DX C257i	v43.04 or earlier	v43.06 or later	✓
imageRUNNER ADVANCE DX C259i	v16.04 or earlier	v16.06 or later	✓
imageRUNNER ADVANCE DX C357i	v43.04 or earlier	v43.06 or later	✓
imageRUNNER ADVANCE DX C357P	v43.04 or earlier	v43.06 or later	✓
imageRUNNER ADVANCE DX C359i	v16.04 or earlier	v16.06 or later	✓
imageRUNNER ADVANCE DX C359P	v16.04 or earlier	v16.06 or later	✓
imageRUNNER ADVANCE DX C3720i	v41.41 or earlier	v41.43 or later	✓
imageRUNNER ADVANCE DX C3725i	v41.41 or earlier	v41.43 or later	✓
imageRUNNER ADVANCE DX C3730i	v41.41 or earlier	v41.43 or later	✓
imageRUNNER ADVANCE DX C3822i	v36.04 or earlier	v36.08 or later	✓
imageRUNNER ADVANCE DX C3826i	v36.04 or earlier	v36.08 or later	✓
imageRUNNER ADVANCE DX C3830i	v36.04 or earlier	v36.08 or later	✓
imageRUNNER ADVANCE DX C3835i	v36.04 or earlier	v36.08 or later	✓
imageRUNNER ADVANCE DX C3922i	v16.04 or earlier	v16.08 or later	✓
imageRUNNER ADVANCE DX C3926i	v16.04 or earlier	v16.08 or later	✓
imageRUNNER ADVANCE DX C3930i	v16.04 or earlier	v16.08 or later	✓
imageRUNNER ADVANCE DX C3935i	v16.04 or earlier	v16.08 or later	✓

Products	Affected Firmware Version	Fix Firmware Version	CVE-2026-1789
imageRUNNER ADVANCE DX C477i	v41.25 or earlier	v41.43 or later	✓
imageRUNNER ADVANCE DX C477iZ	v41.25 or earlier	v41.43 or later	✓
imageRUNNER ADVANCE DX C478i	v36.04 or earlier	v36.09 or later	✓
imageRUNNER ADVANCE DX C478iZ	v36.04 or earlier	v36.09 or later	✓
imageRUNNER ADVANCE DX C5735i	v41.25 or earlier	v41.43 or later	✓
imageRUNNER ADVANCE DX C5740i	v41.25 or earlier	v41.43 or later	✓
imageRUNNER ADVANCE DX C5750i	v41.25 or earlier	v41.43 or later	✓
imageRUNNER ADVANCE DX C5760i	v41.25 or earlier	v41.43 or later	✓
imageRUNNER ADVANCE DX C5840i	v36.04 or earlier	v36.08 or later	✓
imageRUNNER ADVANCE DX C5850i	v36.04 or earlier	v36.08 or later	✓
imageRUNNER ADVANCE DX C5860i	v36.04 or earlier	v36.08 or later	✓
imageRUNNER ADVANCE DX C5870i	v36.04 or earlier	v36.08 or later	✓
imageRUNNER ADVANCE DX C7765i	v43.04 or earlier	v43.06 or later	✓
imageRUNNER ADVANCE DX C7770i	v43.04 or earlier	v43.06 or later	✓
imageRUNNER ADVANCE DX C7780i	v43.04 or earlier	v43.06 or later	✓
imageRUNNER C1533iF*	v10.10 or earlier	v10.20 or later	✓
imageRUNNER C3226i	v8.14 or earlier	v10.20 or later	✓
imageRUNNER C3326i	v16.04 or earlier	v16.06 or later	✓
i-SENSYS C1533iF II	v16.04 or earlier	v16.06 or later	✓
i-SENSYS MF563dw*	v1.01 or earlier	v1.03 or later	✓
i-SENSYS MF832Cdw*	v10.10 or earlier	v10.20 or later	✓
i-SENSYS MF842Cdw	v16.04 or earlier	v16.06 or later	✓
i-SENSYS X C1538 iF II	v16.04 or earlier	v16.06 or later	✓